

# SERVICE



# LETTER

Service Letter No. 353A (Supersedes S. L. No. 353)

February 20, 1961

TO: All Distributors, Dealers, Piper Certified Service Centers and Owners

SUBJECT: Propeller Decal

MODELS AFFECTED: PA-22-108 Colt Airplanes - Serial Nos. 22-8000 to 22-8082 inclusive

DATE OF COMPLIANCE: Prior to but not later than next 25 hours of operation

The decal originally attached to the propellers of aircraft indicated by the above serial numbers is incorrect. The torque value stamped on this decal is 350 inch pounds.

The incorrectly marked decal must be removed and replaced with the correctly marked decal. The correct torque value is 300 inch pounds and the correct model number is M76AM-2, T.C. 1P2. The propeller bolts should be retorqued to assure correct torque value.

Each distributor will receive, with a copy of this Service Letter, a sufficient quantity of the correctly marked decals for compliance with this Service Letter.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "Wes Holmes".

Wes Holmes  
Service Manager

WH:dlt

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.