



# SERVICE BULLETIN

No.721

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

Modification FAA Approved

April 5, 1982

M

Subject: Heater Fuel Regulator Valve Shroud/  
Drain Modification

Models Affected: PA-23-250 (Six Place) Aztec  
Serial Numbers Affected: 27-3050, 27-3154 through 27-8154015

NOTE: Provisions of this Service Release apply only to those aircraft which have Janitrol combustion heaters installed.

Compliance Time: Within the next one hundred (100) hours of operation, or at the next scheduled inspection/maintenance event, whichever occurs first.

Purpose: A field report has been received of a heater fuel regulator valve leaking fuel into the nose compartment. The presence of fuel in this area could present a fire hazard.

This Service Release announces the availability of a kit, the installation of which will allow drainage directly overboard in the event of leakage from the heater fuel regulator valve.

Instructions: All instructions and material required are included in Piper Kit 764 141, Heater Fuel Regulator Valve Shroud/Drain Installation.

Material Required: One (1) each per aircraft Kit 764 141 Heater Fuel Regulator Valve Shroud/Drain Installation.

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This Service Release is effective upon receipt.

Summary: Please contact your Piper Field Service Facility to arrange for compliance with the provisions of this Service Release in accordance with Compliance Time, above.

Any applicable Factory participation will remain in effect for a period of time not to exceed 180 days from the date of this Service Release.

ATA: 2820