



SERVICE No. 300 BULLETIN

Piper Aircraft Corporation
"FAA DOA EA-1 Approved"

Lock Haven, Pennsylvania, U.S.A.
June 3, 1969

Subject: Hydraulic Pump Hose Assembly Inspection

Models Affected: (a) PA-23-250 (Six Place) Aztec "D"
(b) PA-23-250 Aztec series aircraft affected by NOTE, page 2.

Serial Numbers Affected: (a) 27-4060 to 27-4150 incl., 27-4152 to 27-4196 incl., 27-4198 to 27-4209 incl., 27-4211, 27-4212, 27-4214 to 27-4217 incl., 27-4225, 27-4228, 27-4232 and 27-4235
(b) PA-23-250 Aztec series aircraft affected by NOTE, page 2.

Compliance Time: Prior to but not later than the next 100 hours of operation

Purpose: It is necessary to inspect the above referenced affected aircraft to determine the type of hydraulic pump inlet hose presently installed. If the inspection reveals that the hose assembly, Piper part number 17766-05, cannot be identified in accordance with the sketch appearing on page 2 of this bulletin, it must be replaced.

Instructions: See Purpose, above.

Material Required: One (1) each part number 17766-05 hose assembly, identified in accordance with the sketch on page 2 of this bulletin.

Availability of Parts: Piper Dealer

Material Allowance: One (1) each part number 17766-05 hose assembly; comply with Service Publication Compliance/Credit Request procedure.

Labor Allowance: One and one-half (1 1/2) hours for installation of part number 17766-05 hose assembly; comply with Service Publication Compliance/Credit Request procedure.

Material/Labor Allowance Termination Date: March 31, 1970

(over)

Disposition of Parts in Stock:

<u>Part Number</u>	<u>Nomenclature</u>	<u>Quan. (per aircraft)</u>	<u>Code</u>	<u>Remarks</u>
17766-05	Hose Assy.-Hydraulic Pump Inlet	1 each	D	Applies only to part number 17766-05 hose assemblies identified as being manufactured by other than the two manufacturers denoted on sketch below.

Disposition of Replaced Parts:

<u>Part Number</u>	<u>Nomenclature</u>	<u>Quan. (per aircraft)</u>	<u>Code</u>
17766-05	Hose Assy.-Hydraulic Pump Inlet	1 each	D

NOTE

Distributor parts sales records must be reviewed to determine the destination of hydraulic hose assemblies, part number 17766-05, that have been sold from distributor stock subsequent to November 1968. Following the location of affected aircraft as a result of this investigation, the aircraft must be inspected in compliance with the specifications of this bulletin.

