



SERVICE No. 188 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

F.A.A. Approved

May 12, 1960 M

SUBJECT: Positive Locking of Baggage Compartment Doors

MODELS AFFECTED: PA-23-250 Aztecs - Serial Nos. 27-1 to 27-162 inclusive

A more positive engagement of the roll pin and the baggage door latching retainer bushings is necessary.

There are two of these bushings, one each side of the baggage door opening. Each bushing must be shimmed as per the sketch on the reverse side to assure positive locking of baggage door.

Over

Remove retainer bushing (19271)
and shim as required with AN960-516
washers.

Addition of shims may require use
of a longer AN526-1032 machine
screw.

