

SERVICE



LETTER

Service Letter No. 336

June 17, 1960

TO: All Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Modification of Oil Pressure Lines

MODELS AFFECTED: PA-23 and PA-23-160 Apaches Serials 23-1 to 23-1390 inclusive

This Service Letter is to advise that beginning with Apache Serial No. 23-1221 and up a clamp (Tinnerman [A-4980S-3-91]) was installed on the oil pressure line, each firewall, as indicated on the sketch shown on the reverse side of this Service Letter.

Further modification to each firewall was made, beginning with Serial No. 23-1391 and up. This is also shown on this sketch, plate #19148-00.

These modifications were made to provide a more rigid mounting of the oil pressure line on the firewall and to minimize the possibility of cracks or breaks developing in the oil pressure line flares.

This information refers to revision of AD Note 57-10-2 (Revision dated May 24, 1960). This AD note now applies to Serial Nos. 23-1 to 23-1221 as indicated in Service Bulletin No. 152A.

Very truly yours,


PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "Wes Holmes".
Wes Holmes
Service Manager


WH:pz

(Over)

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.



RIGHT HAND INSTALLATION ONLY



19148-00

SERVICE LETTER 336

Note #1 - Use existing screw that attaches firewall to engine mount.