



SERVICE *No. 246* BULLETIN

Piper Aircraft Corporation
Lock Haven, Pennsylvania, U.S.A.

PIPER CONSIDERS
COMPLIANCE MANDATORY.

"FAA, DOA, EA-1 Approved"

March 21, 1967

Subject: Modification of Oxygen Cylinder Rear Retaining Strap
Piper Part Number 758 109

Models Affected: PA-30 Twin Comanches (NOTE: Applicable only to
aircraft that have had an oxygen system installed at
the factory or aircraft that have had Piper Oxygen
Installation Kit 757 100 installed.)

Serial Numbers Affected: 30-853, 30-902 to 30-1470 incl. (See note above)

Compliance Date: Prior to but not later than next 25 hours of operation

Reason For Bulletin: Modification of the oxygen cylinder rear retaining strap
part number 758 109 to preclude the possibility of the
strap rubbing the rudder control cable.

Material Required: None

Modification Instructions: See sketch on reverse side of this bulletin.

Warranty Labor Allowed: None


NOTE

All Oxygen Cylinder Rear Retaining Straps, part number 758 109,
contained in Oxygen Cylinder Mounting Modification Kits, part
number 757 094, (Reference Service Bulletin No. 236) in distributor
or dealer stock must also be modified per this bulletin.

(over)

NOTE

RETAINING STRAP HERE (TOP AND BOTTOM). REMOVE REAR PORTION STRAP AND RUBBER STRIP. 13945-85



246f1

**SERVICE BULLETIN
246**