

SERVICE



LETTER

Service Letter No. 470

April 1, 1966

TO: Distributors, Dealers, Certified Service Centers
and Owners

SUBJECT: Starting Vibrator

MODELS AFFECTED: PA-24-400 Comanches, Serial Nos. 26-1, 26-2,
26-4, 26-5, 26-7 to 26-11 incl., 26-13 to 26-16
incl., 26-18 to 26-46 incl., 26-48, 26-50 to 26-53
incl., 26-55 to 26-59 incl., 26-61, 26-62, 26-64,
26-66 to 26-90 incl., 26-93 to 26-119 incl., 26-122
to 26-148 incl.

A new starting vibrator, part number 492 671, is now available and it is recommended that this vibrator be installed on the above listed aircraft.

The installation of the new vibrator may be accomplished as follows:

1. Remove the present vibrator from its mounting position.
2. Remove and discard present ground wire. (New vibrator has internal ground.)
3. Remove terminals from wires J1D and J1B.
4. Install new terminal clips supplied with vibrator.
5. Install new starter vibrator. Insert J1B terminal to "IN" receptacle and J1D terminal to "BO" receptacle in the vibrator box.

" D I S T R I B U T O R S "

Credit will be allowed for starter vibrator 492 671 on receipt of a Warranty and Credit Claim.

Credit will not be issued for the subject vibrator on any claims received after September 30, 1966.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.