



SERVICE BULLETIN

No. 692

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

Modification FAA/DOA EA-1 Approved

August 6, 1980

M

Subject:

INS

Oxygen Mask Replacement

Models Affected:

PA-31T Cheyenne/Cheyenne II
PA-31T Cheyenne I

Serial Numbers Affected:

31T-7400002 through 31T-8020070
31T-7804001 through 31T-8004040

NOTE:

Only aircraft manufactured between March 18, 1980, and June 1, 1980, with Scott Oxygen Mask, Piper Part Number 474 125 (Scott No. 802896-01) installed and aircraft which have had a mask installed since March 18, 1980, are affected.

Compliance Time:

Within the next one hundred (100) hours of operation or at the next scheduled inspection event, whichever occurs first.

Purpose:

A field report has been received of the discovery of a separated supply line on an oxygen mask assembly. Further investigation has identified specific aircraft and oxygen mask installation affected. If undetected, line separation could result in loss of oxygen supply to user.

This Service Release provides instructions to replace Scott oxygen mask, Piper Part Number 474 125 (Scott Part Number 802896-01).

Instructions:

1. Gain access to the aircraft oxygen masks.
2. Identify affected Scott oxygen masks Piper Part Number 474 125 or Scott Part Number 802896-01).
3. Replace affected oxygen masks with Piper Part Number 474 108 (Scott Part Number 28314-19).
4. Make appropriate entry of compliance in aircraft logbook or Continuous Inspection Manual.

Material Required:

As required, Oxygen Mask, Piper Part Number 474 108.

(over)

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please arrange for compliance with the provisions of this Service Release in accordance with Compliance Time, above.