

SERVICE



LETTER

Service Letter No. 406

September 26, 1963

TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Revision to Owners Handbooks

MODELS AFFECTED: All PA-20 Pacer and PA-22 Tri-Pacer Series Aircraft

Our attention has been directed to an error in the Owners Handbooks for the above models. The handbooks involved are as follows:

Aircraft Model	Handbook Year of Publication	Reference Location
PA-20	1950	Page 48, Item 55
PA-20, PA-22	1952, 1953, 1954	Page 52, Item 55
PA-20, PA-22	1955	Page 54, Item 55
PA-22	1956	Page 50, Item 55
PA-22	1957	Page 52, Item 55
PA-22	1958	Page 52, Item 55

This error appears in the following sentence:

"The nut on the bottom of the screw pulley will take up play if excessive."

This sentence should read:

"The nut on the top of the screw pulley will take up play if excessive."

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "Wes Holmes".

Wes Holmes
Service Manager

WHL:dld

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.