

IMMEDIATE ACTION

SERVICE

NUMBER 169



BULLETIN

February 4, 1959

SUBJECT: Operating Limitations Placard

MODELS AFFECTED: PA-23 Apache, Serial Numbers 23-1502 to 23-1558 inclusive, 23-1560 to 23-1562 inclusive and 23-1565 to 23-1567 inclusive.

The above mentioned airplanes shall have an Operating Limitations placard mounted to the instrument panel face plate directly above the clock.

Service Kit, part number 754 224, will be furnished free of charge through your nearest Piper distributor or dealer. The airplane serial number must be included on all purchase orders.

Until the regulation placard is obtained, the following temporary placard shall be cut out and attached to the instrument panel.

THIS AIRPLANE MUST BE OPERATED
AS A NORMAL CATEGORY AIRPLANE
IN COMPLIANCE WITH THE AIRPLANE
FLIGHT MANUAL. ACROBATIC MANEU-
VERS INCLUDING SPINS PROHIBITED.

End.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.