

SERVICE



LETTER

Service Letter No. 388

November 2, 1962


TO: Distributors, Dealers, Certified Service Centers and Owners

SUBJECT: Removal of Carburetor Heat Shroud Screen

MODELS AFFECTED: PA-23-250 Aztecs, Serial Nos. 27-1 to 27-504 incl., PA-23-250 Aztec (six place), Serial Nos. 27-2000 to 27-2253 incl., PA-23-235 Apache, Serial Nos. 27-505 to 27-517 incl.

A few reports from the field indicate there is a possibility that the subject screen (see sketch below), located on each engine in the outboard exhaust shroud assembly, may over a period of time show evidence of deterioration.

Service experience has indicated that this screen is not necessary, therefore, it is suggested the screen be removed from each engine shroud assembly, on aircraft listed above, at the next 100 hour inspection.



Very truly yours,

PIPER AIRCRAFT CORPORATION

Wes Holmes
Wes Holmes

Service Manager

WH:dld

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.