



# SERVICE No ~~334~~ BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"

March 17, 1971

---

Subject: Alternate Air Hose Replacement

Models Affected: PA-23-250 (Six Place) Turbocharged Aztec

Serial Numbers Affected: 27-4053, 27-4226 to 27-4563 incl., 27-4565 to 27-4579 incl., 27-4581 to 27-4617 incl., 27-4619 to 27-4627 incl., 27-4630 to 27-4636 incl.; turbocharged only.

Compliance Time: Prior to but not later than the next 50 hours of operation.

Purpose: To replace the existing Alternate Air Hoses on the above referenced aircraft with new improved Alternate Air Hoses.

Instructions: Replace existing Alternate Air Hoses with new Alternate Air Hose, Piper part number 48076-02, per the Sketch/Instructions contained on the reverse side of this publication.


Material Required: Two (2) each (per aircraft) Alternate Air Hose, Piper part number 48076-02.

Availability of Parts: Your Piper Dealer.

Effectivity Date: This Service Bulletin is effective March 31, 1971.

Summary: Material for this modification will be provided free of charge by your Piper Dealer providing the compliance time period is adhered to.

(over)



Remove the existing Alternate Air Hose and install new hose, Part No. 48076-02, using existing clamps.

# *Service Bulletin 334*