



Customer Services

SERVICE BULLETIN

No. 160

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.
October 7, 1957

SUBJECT: Stabilizer Attachment Fittings Part 17093-00

MODELS AFFECTED: PA-23, Serials 23-1 to 23-1219 inclusive

Service experience indicates that cracks have been found in the front stabilizer attachment fitting part 17093-00.

A new part, #17093-03, has been designed to eliminate this problem and it is requested that part 17093-00 on the above mentioned airplanes be removed and replaced with part 17093-03 at the next 100 hour inspection or as soon as new parts become available.

These parts will be furnished no charge by your Piper distributor or dealer. Installation of Part 17093-03 will cancel the inspection requirements for this part on C. A. A. Airworthiness Directive 57-13-9.

End
