



SERVICE *No.* 194 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

F.A.A. APPROVED

August 23, 1960

SUBJECT: Replacement of Instrument Panel Face Plate

MODELS AFFECTED: PA-23-160 Apaches - Serial Numbers 23-1871 to 23-1885
inclusive and 23-1888 to 23-1890
inclusive

This Bulletin is to advise that the subject airplanes, as indicated by the above serial numbers, were delivered with an incorrect instrument panel face plate.

A new instrument panel face plate, check list placard and flight manual revised May 23, 1960 will be supplied free of charge for the above listed airplanes. It will not be necessary for you to order this material as it will be handled on an automatic factory distribution basis.

This Bulletin must be complied with immediately upon receipt of the above listed material.

The present flight manual must be destroyed and must be replaced with the one revised May 23, 1960.

A compliance card will be furnished with the material required for this Bulletin and this card must be signed and immediately returned to the factory.

End
