



SERVICE No. 132 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.
January 5, 1955

SUBJECT: Fuel Valve Actuator Handle Locks

MODELS AFFECTED: PA-23, serial 23-1 to 23-100 inclusive

It is requested that the above listed aircraft, not equipped with fuel valve locks, be modified to incorporate Fuel Valve Lock Kit, 754 068.

After the locks have been installed, Service Bulletin Number 127 issued October 15, 1954 can be disregarded, and the pressure cross feed operated per the instructions in the flight manual and on the instrument panel placard.

Fuel Valve Lock Kit 754 068 can be obtained through your Piper Dealer or Distributor at no charge. One hour warranty labor will be allowed upon receipt of a duly executed warranty claim form through the distributor.

SERVICE BULLETIN-132
INSTALLATION INSTRUCTIONS


NOTE-1"
NOTCH BOTH FUEL
VALVE CONTROL HANDLES
AS SHOWN

NOTE-3"
BEND SPRING
SUPPORT AS SHOWN

SK-577-2

NOTE-2"
DRILL FOUR .098
HOLES AS SHOWN

SK-577-3



FUEL VALVE CONTROL LOCK
KIT-754068