

IMMEDIATE ACTION

SERVICE



BULLETIN

NUMBER 131

January 3, 1955

**SUBJECT: Addition of Rubber Extrusion Chafe Strip to Wing
Root Fairings**

MODELS AFFECTED: PA-23, Serial Nos. 23-1 to 23-64 inclusive

It has been found that there is a tendency of the wing root fairings on the PA-23 to chafe the wing skin.

It is requested that the above listed aircraft be modified in accordance with the following instructions and sketch, as shown on the reverse side of this bulletin.

Twenty-two (22) feet of rubber extrusion, Number 827, Piper code number 187 550, is available, at No Charge, through your nearest distributor or dealer. Two hours warranty labor will be allowed upon receipt of a duly executed warranty claim form, through the distributor.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.

