



PIPER

*Customer Services*

# SERVICE No. 150 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

December 21, 1956

---

SUBJECT: Front Stabilizer Fittings - Right and Left - Part 17093-00

MODELS AFFECTED: PA-23 - Serials 23-1 to 23-844 inclusive

It is requested that immediate inspection be made of the two front stabilizer attachment fittings and ascertain that there are three bolts securing each fitting to the longitudinal stringer and the bulkhead (two in the stringer and one in the bulkhead).

If less than three bolts have been used, call the factory Service Department for further instructions.

It will be necessary to remove the stabilizer fairing on the bottom side and use a mirror to make the inspection.

End

---