



# SERVICE LETTER

No. 726

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

August 8, 1974 M

Subject:

Cigar Lighter Placard

Models Affected:

PA-23-235, PA-23-250 and  
PA-23-250 (Six Place) Aztec  
PA-31P Navajo

Serial Numbers Affected:

27-1 to 27-7405399 incl. (24 volt electrical system only)  
  
31P -1 to 31P-7400216 incl.

Compliance Time:

Within the next 100 hours of operation.

Purpose:

To provide placards to be installed in the proximity of the cigar lighter(s) on the above referenced aircraft to caution against use of the cigar lighter receptacles for purposes other than for which they are intended. One each Cigar Lighter Placard, Piper Part No. 80247-02, is required for each cigar lighter, to be installed in accordance with Instructions, below.

Instructions:

1. For instrument panel mounted cigar lighters, locate one each Piper Part No. 80247-02 placard on a horizontal center line and immediately to the right of the cigar lighter.
2. For cigar lighter(s) installed in locations other than the instrument panel, locate one each Placard, Piper Part No. 80247-02 per cigar lighter on the vertical center line and immediately below the cigar lighter.
3. Make appropriate log book entry.

Material Required:

One (1) each per cigar lighter Placard, Piper Part No. 80247-02.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Letter is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to make arrangements for compliance with the provisions of this service release in accordance with Compliance Time, above. Placards required per this service release will be provided free of charge through your Piper Field Service Facility; installation time is negligible.

33/0