

SERVICE



LETTER

Service Letter No. 290

January 21, 1957

TO: All Distributors, Dealers and Owners

SUBJECT: Elevator Horn Bushing Wear

MODELS AFFECTED: PA-23 - Serials 23-1 to 23-640 inclusive

Field Service reports indicate that the elevator horn bushing is wearing abnormally at the point where the rear elevator push-pull tube is attached to the horn.

The Service Department has made up a modification kit so that the latest production installation may be made on the aircraft listed above.

Kit 754 162 is available through your Piper dealer or distributor at a price of \$5.58.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "Rolland Boardman", written over the typed name.

Rolland Boardman
Service Manager

RB:gh

z

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.