



# SERVICE BULLETIN

No. 345

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"

October 7, 1971

---

Subject: Stabilator Bungee Installation

Models Affected: PA-23-250 (Six Place) Aztec

Serial Numbers Affected: 27-4575 to 27-4587 incl., 27-4589 to 27-4620 incl., 27-4622 to 27-4672 incl., 27-4674 to 27-4682 incl., 27-4684 to 27-4694 incl.

Compliance Time: Within the next 50 hours of operation.

Purpose: As a result of a change in type design, it will be necessary to install a stabilator bungee spring (and related parts) on the above referenced aircraft.

This Service Bulletin contains provisions for the material and instructions to accomplish the subject installation.

Instructions: Contained in Piper Kit No. 760 565, Stabilator Bungee Installation.

Material Required: One (1) each (per aircraft) Kit No. 760 565, Stabilator Bungee Installation.

Availability of Parts: Your Piper Dealer.

Effectivity Date: This Service Bulletin is effective October 15, 1971.

Summary: A ~~postage paid, self-addressed~~ "Compliance Certification" card is ~~enclosed~~, to be filled out by the aircraft owner/operator and returned to Piper Aircraft Corporation immediately subsequent to completion of this modification.

Material for this modification is available free of charge through your Piper Dealer providing the Compliance Time provisions are met. Two (2) hours per aircraft labor allowance is also provided.

---