

SERVICE



LETTER

Service Letter No. 326

December 28, 1959

TO: Distributors, Dealers and Piper Certified Service Centers

SUBJECT: PA-23 Elevator Tab

The Apache elevator, Part No. 19446, has been modified by the installation of a tab at the trailing edge of the elevator.

Elevators ordered through the Service Spares Division for service replacement will have this tab and may be installed on all models. When replacing one elevator, it will not be necessary to replace the one remaining or install another tab to match up.

The tab may be adjusted manually to compensate for any changes in flight characteristics that may be noted. The adjustment of this tab will vary the tension on the springs used in the bungee system as this tension may be subject to slight changes during the operation of the aircraft.

Very truly yours,

PIPER AIRCRAFT CORPORATION

Wes Holmes

Wes Holmes

Service Manager

WH:mm

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.