

SERVICE



LETTER

Service Letter No. 239

January 3, 1955

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: PA-23 Cabin Draft

MODELS AFFECTED: PA-23, Serials 23-1 to 23-15; 23-17 to 23-28;
23-30 to 23-46; 23-48 to 23-59; 23-61 to 23-64;
23-67 to 23-72; 23-74; 23-75; 23-77 to 23-85;
23-87 to 23-90.


There is a draft condition existing in the cabin of the PA-23 Apache, causing the rear seat occupants to be uncomfortable during cold weather operation.

This draft is also the cause for a certain amount of seeming malfunctioning of the cabin heater.

A draft proofing kit, number 754 078, and installation instructions, are available through your nearest Piper distributor or dealer at No Charge. Three hours warranty labor will be allowed to comply with this letter.

Very truly yours,

PIPER AIRCRAFT CORPORATION


Rolland Boardman
Service Manager

RB:pf

z

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.