



PIPER

Customer Services

SERVICE *No. 130* **BULLETIN**

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

December 31, 1954

SUBJECT: PA-23 Heater Fuel Line

MODELS AFFECTED: PA-23, Serials 23-1 to 23-15; 23-17 to 23-28;
23-30 to 23-64; 23-67 to 23-72; 23-74 to 23-94
and 23-98

There have been several instances reported involving breakage of the heater fuel line at a point where the line enters the heater fuel strainer, which is located on the bulkhead above the battery.

It is requested that the heater line on the above airplanes be modified to incorporate the use of a flexible hose. Kit No. 754 079 is available through your nearest Piper distributor or dealer at No Charge. Thirty (30) minutes warranty labor will be allowed and will be paid only upon receipt of a duly executed warranty claim form through the distributor.

End
