

# SERVICE



# LETTER

Service Letter No. 323

November 23, 1959

TO: Comanche Owners, Distributors, Dealers and  
Piper Certified Service Centers

SUBJECT: Defroster Operation

MODELS AFFECTED: All PA-24 Comanches

The efficiency of the windshield defroster system will be improved by removing the two perforated buttons, part number 21630, in the defroster outlet.

These buttons must be re-installed during mild weather as the perforations prevent a concentration of heat on the windshield which will distort the plexiglass.

Very truly yours,

PIPER AIRCRAFT CORPORATION

*Wes Holmes*  
Wes Holmes  
Service Manager

WH:mm

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.