



SERVICE LETTER

No. 605

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

February 7, 1972

Subject: Reissue of Aircraft Owner's Handbook

Models Affected: PA-24-260 Comanche Turbocharged

Serial Numbers Affected: 24-4904 to 24-5001 incl. (Turbocharged Only)

Compliance Time: Immediately upon receipt of material.

Purpose: To provide a reissued aircraft owner's handbook for the above referenced aircraft containing revised performance data, emergency procedures, power and range charts and various miscellaneous revised data. Provided with the reissued Aircraft Owner's Handbook is a revised Power Setting Table for the above referenced aircraft.

It is the further intent of this service publication to announce the obsolescence of the original issues of the above referenced aircraft owner's handbook and power setting table, and to remove all original issue copies from service.

Instructions:

1. Replace existing owner's handbook with July 1971 issue.
2. Replace existing power setting table with reissued version, date coded "711005" (denoted in the lower right hand corner of the table).
3. All copies of PA-24-260 Turbocharged Comanche Owner's Handbook part number 753 823 dated prior to July 1971 and Rajay Turbocharged Lycoming IO-540-R Series Power Setting Table, part number 230 754 dated prior to date code 711005 are to be restricted from further use and destroyed.

Material Required:

1. One (1) each (per aircraft) part number 753 823 Owner's Handbook, Complete Revision No. CR710708.
2. One (1) each (per aircraft) part number 230 754 Power Setting Table, Revision Date Code 711005.

(over)

Availability of Parts:

A copy of the above referenced Owner's Handbook and Power Setting Table is enclosed for each affected owner, according to our FAA owner registration listing. Material for aircraft not appearing on the FAA owner list will be issued to the Piper Distributor to which the aircraft was originally delivered.

Additional copies of the reissued owner's handbook and power setting tables are available in the usual manner through your Piper Dealer.

Effectivity Date:

This Service Letter is effective February 18, 1972.

Summary:

Subsequent to receipt of this service publication with enclosed owner's handbook and power setting table, please complete and return the compliance card which has been inserted under the front cover of each owner's handbook.