

SERVICE



LETTER

Service Letter No. 310

November 10, 1958

TO: All Distributors, Dealers, Owners and Operators

SUBJECT: Locking of Landing Gear Motor Release Arm

MODELS AFFECTED: PA-24 and PA-24 "250"
Serial Numbers 24-1 to 24-504 inclusive

The safety wire used to hold the landing gear retraction motor release arm in a closed position shall be replaced on the above mentioned airplanes by an elastic strap, part number 21836-00, per sketch on the reverse side of this letter.

This elastic strap can be obtained from your nearest Piper distributor free of charge until June 1, 1959. To secure this material free of charge it will be necessary that the aircraft serial number or numbers be included on all purchase orders.

No warranty labor will be allowed.

Very truly yours,


PIPER AIRCRAFT CORPORATION

A handwritten signature in cursive script, appearing to read "Rolland Boardman", is written over the typed name.

Rolland Boardman
Service Manager

RB:mm

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.



ELASTIC STRAP
21836-00

GEAR MOTOR RELEASE HANDLE
STRAP INSTALLATION

SERVICE LETTER

NUMBER 310

PIPER AIRCRAFT CORPORATION

LOCK HAVEN, PENNSYLVANIA