



# SERVICE <sup>No. 191</sup> BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

June 16, 1960

---

**SUBJECT:** Aileron Hinge Bracket - Part No. 20211-00

**MODELS AFFECTED:** PA-24 and PA-24-250 Comanches  
Serial Nos. 24-1 to 24-1243 inclusive

**COMPLIANCE DATE:** Prior to but not later than next 100 hour inspection.

It has been brought to our attention in a recent report from the field that a crack was discovered in one of the subject aileron hinge brackets, part number 20211-00.


This report is an isolated case, however, we feel that a visual inspection of these brackets should be made on all Comanches as indicated by the above serial numbers and any cracked brackets should be replaced.

Reference to the sketch on the reverse side of this bulletin will indicate the location of these brackets.

Compliance with this inspection will not require additional inspections other than those normally made on the routine 100 hour inspection.

Over

---



SERVICE BULLETIN 191