



SERVICE LETTER

No. 719

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

August 28, 1974

ATA 7610

Subject: Throttle Control Cable De-Icer Boot Installation

Models Affected: PA-31P Navajo

Serial Numbers Affected: 31P-1 to 31P-7400227 incl.

Compliance Time: Within the next 100 hours of operation.

Purpose: It has been reported that the throttle control cables in the proximity of the throttle cable arm can accumulate moisture in the cable core. Should the aircraft be exposed to extremely low temperatures, accumulated moisture in the cable may freeze, impeding operation.

This service release provides instructions to (1) purge any possible moisture from the cables and (2) install a de-icer boot over the engine end of the cables - to preclude accumulation of moisture.

Instructions: Contained in Piper Kit No. 760 874, Throttle Control Cable De-Icer Boot Installation.

Material Required: One (1) each per aircraft, Piper Kit No. 760 874, Throttle Control Cable De-Icer Boot Installation.

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This Service Letter is effective upon receipt.

Summary: Please contact your Piper Field Service Facility to make arrangements for compliance with the provisions of this service release, in accordance with the recommendation in Compliance Time, above. Material specified above is being made available free of charge through your Piper Field Service Facility, as long as the installation is accomplished by a Piper Field Service Facility.

A Service Publication Compliance Form is enclosed with each copy of this service release mailed to affected owners of record; this form is to be filled out according to Instructions on the form reverse side and left with the Piper Field Service Facility performing the modification.
