

VENDOR SERVICE PUBLICATION

February 25, 1977

TO:   X   All Piper Distributors  
  X   All Piper CORPAC's  
       Affected Aircraft Owners/Operators  
       All of the above

SUBJECT: AVCO Lycoming Service Bulletin No. 406, "Romec and Titan Fuel Pump Inspection".

Models Affected:

Serial Numbers Affected:

PA-23-250 (6 Place) Aztec.....	27-4053, 27-4226 and up (Turbocharged)
PA-31 and PA-31-325 Navajo.....	31-2 and up.
PA-31-350 Navajo Chieftain.....	31-5001 and up.
PA-31P Pressurized Navajo.....	31P-1 and up.


Purpose: To provide distribution of the attached Service Publication (identified in SUBJECT, above) to Piper Field Service Facilities and, if applicable, to affected Piper owners/operators.

Detailed instructions relative to compliance action are specified on the attached Service Publication; any additional/supplemental data, if necessary, is contained in the following "Special Instructions" section.


Special Instructions:

Insure that your respective Field Service Facilities are aware of the provisions of the subject vendor service release.





ROMEc  
RG-9080  
FUEL PUMPS



Romec & Titan Fuel Pumps Showing Applicable Attaching Screws and Orientation of Lockwire